



1/11

FIG. 1




2/11




3/11

FIG. 3



4/11

FIG. 4



5-6-7





FIG. 6


The diagram illustrates a multi-pitch feeding mechanism (90) for a printing press. It features a main horizontal shaft (100) with various components mounted on it. On the left, a light chamber (92) and a dark chamber (94) are shown. The mechanism includes a series of rollers (102, 104, 106, 108, 110, 112, 114, 116a, 116b, 118, 120, 122, 124, 126, 128, 130, 132, 134, 136, 138, 140, 142, 144, 146, 148, 150, 152, 154, 156, 158, 160, 162) and a series of servomotors (150, 151, 152, 154) driven by servomotor drivers (156, 157, 158, 160). A controller (162) is connected to the servomotor drivers. The mechanism is designed to feed material in two different pitches (2 and 1) at the same time. The diagram is labeled with various reference numerals (e.g., 40, 42, 44, 46, 48, 50, 52, 54, 56, 58, 60, 62, 64, 66, 68, 70, 72, 74, 76, 78, 80, 82, 84, 86, 88, 90, 92, 94, 100, 102, 104, 106, 108, 110, 112, 114, 116a, 116b, 118, 120, 122, 124, 126, 128, 130, 132, 134, 136, 138, 140, 142, 144, 146, 148, 150, 152, 154, 156, 158, 160, 162) and includes a date stamp 6/11.

7/11

FIG. 7



8/11







9/11

FIG.9

170



10/11



11/11

FIG.11

